



Schindler Precaution Package

Increased safety for passengers



Schindler Precaution Package

Increase safety for passengers



Be prepared for an unexpected power outage. It's important to have a plan in place for the safety and comfort of your elevator passengers. Our Precaution Package ensures safe exiting of passengers even in the absence of an electrical supply.



Your benefits at a glance

- Ensure safe exiting of passengers during the event of a power failure to improve passenger safety and comfort
- Installation reduces passenger entrapments
- Battery power is supplied to move the elevator

The package includes:

Automatic rescue device

- Battery Backup Power Supply.
- Elevator Software and Sensors to enable the lift to move under battery power.

Functionality includes:

- In the event of a power failure, the elevator moves and stops at the nearest floor and then the doors will open to ensure safe exiting of passengers.
- The elevator is then placed out of service pending restoration of normal electrical service.
- This device prevents passengers being trapped inside an elevator during a power failure.
- Rather than being inconvenienced for an indeterminate period of time pending the arrival of a service technician during a power blackout, the passengers are automatically released within seconds.

Other available option packages



Moving



Security



Penthouse



Office



Low consumption

Schindler Lifts Australia Pty. Ltd.
T: 1300 WE ELEVATE (1300 933 538) | E: schindlersales@au.schindler.com | W: www.schindler.com

This publication is for general informational purposes only and we reserve the right at any time to alter the services, product design and specifications. No statement contained in this publication shall be construed as a warranty or condition, expressed or implied, as to any service or product, its specifications, its fitness for any particular purpose, merchantability, quality or shall be interpreted as a term or condition of any service or purchase agreement for the products or services contained in this publication. Minor differences between printed and actual colors may exist.